SPECIAL REPORT · Site round

Safety round

Sample Project · Pumping Station

+ 2 | ! 1 | x 1

Date	To	Prepared by	Points
21 Nov 2026	HSE Manager		4

1 Open cable trench


E300 ISSUE



No barriers or signs along the open trench — to be fenced today.

2 Pipe rack lifting zone

P340 FOLLOW-UP






Barricade the zone under the rack during erection.

3 Shelter & headers

A300 OK





Access clear, housekeeping good.

4 Evaporation pond

EP01 **OK**



Dike wall complete, edge protection in place.

Summary: 2 OK · 1 follow-up · 1 issue

Prepared by · Site Engineer · Sample Contracting Co.