
Area photo history

Sample Project · Pumping Station · C100 · Pump Foundations

Area	Contractor	From	To	Photos	Days
C100	Contractor A (Civil)	19 Nov 2026	21 Nov 2026	3	2

19 Nov 2026 1 photo(s)




Foundation works — in progress
Pump block foundations stripped

21 Nov 2026 2 photo(s)



Backfilling — in progress
ردم الطبقة الثانية حول قواعد المضخات



Compaction — in progress
Compaction around pedestal footings

Prepared by · Site Engineer · Sample Contracting Co.